Contractor's Quality Control Report/Quality Assurance Report

(ER 1180-1-6)
Contract Number UPC/Project Title and Location of Work
DACA85-01-C-0026 FY01 Replacement Family Housing, Fort Wainwright, Alaska CQC Report Number Date Contractor
Osborne Construction Company
080 Friday August 2, 2002 3701 Braddock Street
Fairbanks, Alaska 99707
Weather Classification:
CLASS A No interruptions of any kind from weather conditions occurring on this or previous shifts CLASS B Weather occurred during this shift that caused a complete stoppage of all work. CLASS C Weather occurred during this shift that caused a partial stoppage of work. CLASS D None results of previous adverse weather. CLASS E Weather overhead excellent or suitable during shift but work partially stopped due to
previous adverse manner.
OTHER Explain.
Classification: A Temperature: Max +76F Min +52F Precipitation: sunny
Contractor/Subcontractors Work Activities Performed Today: (Attach list of equipment either idle or working as appropriate)
Reference (NAS ID No.) Activity Activity Activities if enormed Today. (Adact list of equipment either idle of working as appropriate)
Work Performed This Day: (Include location and description of work performed. Refer to work performed by prime and or subcontractors by NAS activity number in the section above).
Building 1402:
OCC performing general clean up around site.
Building 1404: OCC continuing pick up work and correction on stairs.
Building 1405: OCC continuing pick up & general clean up. Slayden continued plumbing rough in. ECCI continuing installation of boxes and
other rough-in.
Building 1406: OCC placed concrete for stem walls and utilidor connecting 1406 to 1408. Building 1407: OCC continuing setting wall panels on 2 nd floor, building stairs and fire-blocking on 1 st floor. Also installing Simpson A35
brackets.
Building 1410: OCC setting 2 nd floor beams and joists.
Building 1411: OCC placed and finished concrete for footings.
Building 1408: OCC applying water proofing to branch utilidor and setting lids, sealing with oakum and mastic. Building 1409: Slayden laying out for core drilling.
Building 1412: OCC installing sill plates and anchor bolts and stripping wall forms from mechanical room entrance and applying waterproofing.
Building 1414:
Building 1416: OCC continued applying Thoroseal waterproofing. Building 1419:
MH 1063A: OCC forming utilidor slab from MH 1063A heading west. Slayden completed steam tie-in to main at MH 1063, setting the valve
and Hyspan compensator.
OCC cleaning out utilidors between buildings 5 & 6 as well as main utilidor along Dogwood St. prior to inspection by Charlie Davenport of DPW. Slayden started demolition of Fire Hydrant at 100 th and Dogwood, unable to remove from concrete below grade.
Great Northwest continued excavation of main utilidor along 100 th St
Materials Received to be Used and/or Incorporated into Project.
materials received to be osed and/or incorporated into Project.
Quality Control Inspections Performed This Date: (Include inspections, results, deficiencies observed, and corrective actions.)
Preparatory Prep Inspections on TS 02510 Storm Drains and TS 07310 Asphalt Shingles (see attached)
Follow-up Follow up on carpentry: QC Jim Frink continuing follow up inspection of rough carpentry in building 1405 units C & D. working with
Project Engineer Jerry Love and General Foreman Matt Emerson to correct deficiencies and to consult with engineers/architects to clarify
discrepancies in plans and specs. Follow up on concrete: Rebar has adequate clearances (1-1/2" from forms, 3" from grade), supported by sufficient dobies with 40 diameters lap.
Observed laborer stinging concrete incorrectly, informed concrete foreman who corrected laborer and demonstrated and instructed in proper
stinging procedures.
Follow up on mechanical: Slayden continuing steam piping in utilidor 1063 to 1063A, using welding rod from plastic, water tight rod holder, using 6010 root pass, 7018 cover pass, on socket words, 6010 root pass, 7018 cover pass, on socket words, 6010 root pass, 7018 cover pass, on socket words, 6010 root pass, 7018 cover pass, on socket words, 6010 root pass, 7018 cover pass, on socket words, 6010 root pass, 7018 cover pass, on socket words, 6010 root pass, 7018 cover pass, on socket words.
using 6010 root pass, 7018 cover pass on socket welds, 6010 root pass, 6010 hot pass and 7018 cover pass on butt welds. Follow up on mechanical: Received from Slayden, the welding x-ray report from NDE regarding the two welds which failed and which were re-
done and re-x-rayed along with four other welds (see attached).
Was the construction deficiency tracking list updated this date: XYes No □

Date Friday August 2, 2002

Contractor Quality Control/Quality Assurance Report Continued FY01 Replacement Family Housing, Fort Wainwright Alaska

	DACA85-01-C-0026	
Tests Required by Plans and/or Specifications	Performed and Results of Tests (COC)-	

Type of Test Slump, air and cyli	Method nders (see attached)	Results		
Verbal Instruction	ns Given/ Received:	(List any instructions given by Government. Inc	clude names, reactions, and re	emarks.)
Verbal Writ	ten			
			•	
Work Progress:	Are there any Gove	ractor caused delays or potential finding or ernment caused delays or potential finding eseeable or weather related delays?		No No No
	·			
Foreman Matt Eme O.C. lateral bracing o.c. is considered a placement of conci- be taking out of set his crews and that Utilidor inspection of buildings 1412 & 1 QC verbally informa- finished continuous	erson, and Pete Van y", Pete Van Husin di a rigid ceiling and the rete at MH 1063A. Ir rvice, the fire hydrant it shouldn't be a prob with Charlie Davenpo 409. Charlie Davenpo ed by General Forerr s soffit vent will now r	scellaneous remarks pertinent to work): In Husin (SBS Truss Designer) discussing the disconsiment hat a single layer of 5/8" gypsurefore, bottom chord bracing is not requireformed Chief Brady of the Fort Wainwright at the comer of 100th St. and Dogwood (tolem, and to notify him again when it is bart, Steve Eldridge of Slayden and Superinort approved placement of utilidor lids for han Matt Emerson that detail 7 of DWG Aun from bottom of facia, horizontally (not	he note on truss shop draw um board screwed off to the ed. Quality Control from Unit Fire Department that Of within OCC fenced off are ack in service. Intendent Jeff Crawford for these utilidors. 5.1 has changed per Tom inclined with pitch of roof).	wings "Rigid Ceiling applied or 6'-0" ne bottom chord of the trusses at 2'-0" University Redi-Mix (Jack) on site for CC subcontractor Slayden P&H will a). Chief Brady said he would inform a branch utilidors and main between Vasilatos (VP OCC). The pre-
Safety: (Include any No Discrepancies r	Infractions of approved noted.	safety plan, safety manual, or instructions from	Government personnel. Spec	ify corrective actions taken.)
Contractor's Certi during this reporting pr	fication: I certify that t eriod were in strict comp	he above report is complete and correct and tha liance with the contract/plans and specifications	it all materials and equipment except as not above.	used, work performed and tests conducted
Contract Quality C	Control Manager Sig	mature Chris Se	eleu Date	Friday August 2, 2002

Additional comments or exceptions:

No 🗌 No 🗍

QAR Signature

Supervisor's Initial

Site Superintendent Signature

Government Quality Assurance Comments

Quality Assurance Testing Performed this date? Yes Safety Inspections performed other that noted above.

Concurs with the CQC Report? Yes ☑ No ☐

Contractor Quality Control/Quality Assurance Report Continued FY01 Replacement Family Housing, Fort Wainwright Alaska DACA85-01-C-0026

		•	· · · · · · · · · · · · · · · · · · ·		
Manpower and Equip	ment				
1 atau			Osborne Construction Company		
Labor Classification Project Manager Superintendent General Foreman QCSM QC Carpenters Operator Laborers Project Engineer Field Engineer SBS Field Engineer Welder	Number 1 1 1 1 1 47 3 22 2 2 1 1 Total Hou	Hours 12 14 12 10 11 423 27 198 18 20 10 6 urs: 770	Fequipment Make/Model Rate Year Ford pickup 2000 Chevy pickup 2000 Chevy pickup 2000 Mazda Pick up 1991 Grove RT60 Hydro crane SBS Boom Truck Flat-Deck Trailer 2000	Number Ea. 1 1 1 1 1 1 1	Hrs/Days Used 9 12 10 9 9 9
		Great No	thwest		
Labor Classification Superintendent	Number	Hours	Equipment Make/Model Rate Year Dodge Dsl 2000	Number Ea. 1	Hrs/Days Used
Assistant Super. Carpenters Labor	0	0	TD 7 Dozer excavator Komatsu	1 1 1	hrs 8 hrs
Operator Surveyor Electricians	0	16	Dozer 650 H 416 Excavator Dump Truck	1	8 hrs 0 hrs hrs
FORMAN Drivers	0 .	0	rolling compactor Water Truck caterpillar JD 550	1 1 1 2	8 hrs 8 hrs hrs 0 hrs
			Side dumps	2	Ullis
Labor	Total Hou	urs: 16	Montauk Environmental Equipment		
Classification Enviro. Specialist	Number	Hours	Make/Model Rate Year PID Snifffer MicroTip 2000 4-door sedan	Number Ea. 1 1	Hrs/Day Use
	Total Hou	ırs:			
Labor			Stutzman Engineering Equipment		
Classification Surveyors	Number	Hours		Number Ea.	Hrs/Day Use
	Suburb Total Hou		1 hrs		
	rotal Hot	irs.			
			Slayden Plumbing & Heating		
Labor Classification Superintendent Plumber Apprentices Welders Insulators Cert. Welding Inspec	Number 1 6 4 1 tor Total Hou	Hours 8 . 48 32 8	Equipment Make/Model Rate Year Pick up Pick up Welding Machines	Number Ea. 1 1 2	Hrs/Day Us 8 8 16

Contractor Quality Control/Quality Assurance Report Continued FY01 Replacement Family Housing, Fort Wainwright Alaska DACA85-01-C-0026

Labor			Equipme	nt			
Classification Superintendent Operator Drivers	Number	Hours	Make/Model Excavator Semi End dump Low boy	Rate Hitachi	Year	Number Ea.	Hrs/Day Us
	Total Hou	ırs:					•
Labor			Environmental Solut Equipme				
Classification Owner Foreman Air Monitor	Number	Hours	Make/Model Van Truck Cube Van truck	Rate	Year	Number Ea. 1 1	Hrs/Day Use 0 0
Operator laborers						0 0	0 0
	Total Hou	ırs:					
Labor			Concrete Cutters Equipme				
Classification Concrete Cutters	Number	Hours	Make/Model Box Van Air Compressors	Rate	Year	Number Ea. 1 1	Hrs/Day Use
	Total		ECCI (Electrical Su	ıb)			
Labor			Equipme				
Classification Owner/foreman	Number 1	Hours 8	Make/Model Dodge Pick up	Rate	Year	Number Ea.	Hrs/Day Use
Electrician laborers	1	8	Chevy Pick up Bucket/Pole Settir	½ ton ng truck	99	1 2	9 16
	Total Hours Sub Total			_			
	Previous:	35,583.0					
	HTD	36 481 O					

UTD: 36,481.0



Phone: 562-2000, Fax: 563-3953

CONCRE	TE&A	IASONR ar 🚨 Gro	LY out
Dispatch Date:	Anict	2 2002	

Dispatch Date.	marit a cook
Dispatch Time:	0700
	Page \ of \

Client: Osborne Project: FIOI Wainweight Family Order taken by: Requested b	y:		W.O. MOA Perm Date:	it # Time:
Test Locations Selected by:	Contractor	Owner	Tested by/date:	AS 8/2/02
Time Departed for Site:	Notification of Test Re Time Arrived Site:	0710	Date:	Skeis Boy 8-2-02 1130
Time Departed Site: 11.35	Time Arrived Back: _	11 42	rame:	use
Standby Requested by (start/end):	Total Dove Wals	ime: \30 ₇	Time Pour	Started: 0730
Contractor: Osborne	Total Pour Volu			
Supplier: University Red: Mix	Product Code:			Ended: 1200
Specifed: Strength' 28 Man	Air 5-7%.	Slump	50-100mm	w/c
Other:				

encearbn.doc

Checked by/date:

Today's Set No.	1	2	Location
Total Air	-5.4	6.0	1) Walls of Bldg. 1406 25m5 2.5mE of
Agg. Corr.	_	-	NE Corner of Bldg.
Entrained Air	5.4	6.0	
Slump	85 mm	90mm	2) Footings of Bldg. 1411 Z5mW of NE
Conc. Temp.	20,52	205%	(orner of Bldg. 1411 Z5mW of NE
Pour Air Temp.	22.22	22.20	
Σ yd ³ Poured	12/18	21 / 27	placed by pump truck
Ticket No.	30531	30536	campled from truck rear discharge
Size/No. Specimens	6x12/8	6,12/8	

Remarks:	 			
			·	
	1			
		•	·	
I ·				

Cylinders P	icked Up
by/date: 4	45 8-3-02
site visit:	TM ,5
max/min te	mn. 75/50

☐ Unit Price ☑ T & M

Preparatory Phase Checklist

inable Feature:		ontract No.: FY01 Family Housing Fort Wainwright Alaska		Date: ####################################		
		nalt Shingles				
ernment Rep Notifie	ed	Not Available	Hours in Advance	Yes	No	
1.0						
ersonnel Present:		D	tu	0		
<u>Name</u>		<u>Pos</u>	ition	Com	oany/Government	
Chris Seeley		QC Manager		OC	C	
Jeff Crawford		Superintendent		.00		
3) 107	e vson	Owner		4	1 Roosing	
Paris Po	terran	Foreman	· · · · · · · · · · · · · · · · · · ·	Ω_{-}	1 Rocking	
uning ne	1.00 2011				- Masing	
						
				· · · · · · · · · · · · · · · · · · ·		
ubmittals	· · · · · · · · · · · · · · · · · · ·					
eview submittals ar	nd/or submittal lo	g. Have all submittals	been approved?			
Yes	ia or out muario	No	X			
If not, what items	have not been s					
ii not, what items	nave not been so	abillitted?				
Cubmittala ara in						
Submittals are in	review			· · · · · · · · · · · · · · · · · · ·	·	
re all materials on h	nand?	Yes	N	lo X		
If not, what items	are missing?			a	A	
,		1 /4	ר:	< / /		
ice sh	ield	-rell r	now onsit	e w/shi	ngles	
onthe	May	•		l		
	1					
	•	·				
heck annroved sub	mittale againet de	olivered material (This	should be done as material	arrivae)		
noon approved out	mittalo agamot a	Silvorod Material. (Tric	should be done as material	annvos.)		
Comments:	This will be see	omnlish e d				
Comments.	This will be acc	omplished				
laterial storage						
Are materials stor	ed properly?	Yes	N	lo [`]		
If not, what action	is taken?	This will be accom	plished			
7	- /.	10+1	- (1 7	
Review Plans	ce shie	eld wobe	rug up the	any voot a	ep <u>aa jace</u> nl	
//	nimum	of 6" B	Ridge venty	does not a	10 la 2-hour	
Comments: //	1/1	+ 11 min	of of	ning -	Canada	
FAT ACE	all bu	c will vum	viage vent	<u>cominacas</u>	Jor desched	

QC REP

July 26, 2002



FY01 REPLACEMENT FAMILY HOUSING PROJECT DACA85-01-C-0026

Submittal Review Letter KAI No. 20133

Osborne Construction Company 3701 Braddock Street Fairbanks, Alaska 99707

Attn: Chris Seeley, QCSM

Re:

Transmittal No. 07310-1 (Perimeter Underlayment Membrane)

Dated: 07-22-02

We received the above noted submittal via fax on 7/20/02 (Saturday). We have reviewed the material submitted. This submittal is being returned to you as stamped and signed below.

Notes as follows:

- 1. ArmourGard application directions indicate "end laps must be at least 15cm (6 in.). This brought to our attention a typographical error in paragraph 3.2.1 of the Specifications. The error is in the conversion of 157mm to inches. 157mm converts to 6" and not 4" as indicated. Follow manufacturers instructions of 6" of end lap.
- 2. This submittal review is for item 1.1.2 of the Specifications only. Other items specified in 1.1 have not been received for review.

End of Submittal Review by: Mike Griffith, KAI

SHOP DRAWING RE	VIEW							
MO EXCEPTIONS NOTED	RESPONSE RECURRED							
N ENCERNORS NOTED: PURPORAL AS CORRECTED	PRIME CONTRACTOR(S)							
EXCEPTIONS NOTES: REVISE AND RESUGNIT	RESLEMEN							
LINACOSPIABLE REGLEMENT	DATE							
RESUMB COPY	DATE							
THE REVIEW OF THE SHOP DRAWING COSS NOT THE RECURSIONS, MAY DEVIATION FROM THE CONTRI RECURSIONS, MAY DEVIATION FROM THE CONTRI SPECIFICALLY SPOUNDED TO THE ATTENTION OF THE UPON THE DRAWINGS, OR BY APPROPRIATE CHANGE	ARCHTECT IN WRITING AND E ORDER.							
DOTE 7-26-62 SIGNED WHILE CALLS								



A-1 Roofing and Insulation, Inc.

Darrell Peterson, Contractor * 2095 Frank Avenue * Fairbanks, Alaska 99701 (907) 452 Roof (FAX (907) 451-6958 * License # 18586 * Bonded * Insured

SAFETY REQUIRMENT

Job:

FY01 - Replacement Family Housing

Sub to: Osborne Construction

Location:

Ft. Wainwright, AK

Date:

August 2002 to Completion

Off Job Site

Safety meetings to be held on a weekly basis. All employees are required to attend.

2 Employees are required to sign attendance sheet in verification of their attendance and confirming understanding of subject matters discussed.

On Job Site

- 1 All ladders must be secured and tied off
- 2 ONE man only to each anchor
- 3 All workers to wear full harness
- 4 Hard hats worn at all times. (Wear cotton kerchief under them if they cause you to perspire. There is NO exception to this rule.)
- 5 Shirts must be worn at all times. (Wear a lightweight cotton shirt if it is hot. They will help keep you cool.)
- 6 NO material to be carried up ladder
- 7 NO alcohol consumed on the job
- 8 Absolutely drug free environment
- 9 All workers must wear safety glasses

Other Requirements

- A copy of this notice must be maintained in company vehicles on job site
- 2 A copy of this notice must be posted in office
- Each employee must sign and verify they have read, they understand, and they will comply with these requirement. Failure to do so will mean exclusion form the jobsite.

I have read and understand the noted requirements	and with my sign	nature confirm	I will comply.	
Signed this 3 day of Ava, 2002	1	\	PL)
Signed this 2 day of 7 4 , 2002	(print name)	Jan ren	terser.	<u> </u>
		5 /	1	
Telephone Safety Numbers on back:	Signature:	avven	elerson	
	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~			

# Emergency Reporting of On the Job Accident

Doctor: 911

Ambulance: 911

Hospital: 911

Police: 911

Fire Dept. 911

Other:

Office: 452-7663

After Office Hours: Dottie 456-7383

Darren 452-4522

- Report accident immediately to foreman
- Foreman report accident immediately to Management
- Inform medical personnel injury is Worker's Compensation Insurance
- Obtain worker's compensation report forms from office
- Submit worker's compensation forms within three working days.

# JOB HAZARD ANALYSIS (JHA)

Phase of Construction:	Roofing FY101 - Replace	Replacement Housing FWW	A-1 Roofing & Insulation, Inc. PO Box 82449
Page one of one	Subcontractor to Osb	to Osborne Construction	Fairbanks AK 99708 (907) 452-7663
ACTIVITY	HAZARD	METHOL	METHOD(s) OF PROTECTION
Installation	Slips and Falls from Roof	<ol> <li>Keep roof work area clean and use catch boards at edge.</li> <li>Review with all affected employees the fall protection pla</li> <li>Require all employees to wear appropriate fall arrest equat all times.</li> </ol>	Keep roof work area clean and use catch boards at edge. Review with all affected employees the fall protection plan for this project. Require all employees to wear appropriate fall arrest equipment and be tied off all times.
·	Slips and Falls from Ladders	<ol> <li>Inspect ladders for good condition.</li> <li>Ladder shall be equipped wit good condition.</li> <li>Ladder shall have firm footin inches above landing.</li> <li>Never climb or descend a ladhand line.</li> <li>Never use a step ladder as a lapart and in a locked position.</li> </ol>	<ol> <li>Inspect ladders for good condition prior to start of each shift.</li> <li>Ladder shall be equipped with safet feet, rungs sound and in place, and rails in good condition.</li> <li>Ladder shall have firm footing and be secured to the structure, extending 36 inches above landing.</li> <li>Never climb or descend a ladder with anything in your hands or pockets; use hand line.</li> <li>Never use a step ladder as a ladder, and operate only with legs spread fully apart and in a locked position.</li> </ol>
	Slips and Falls from Scaffolding	<ol> <li>Properly erected.</li> <li>Use of fall protection.</li> <li>Proper railing and toe boards in use.</li> </ol>	s in use.
	Cutting and Stapling the Roofing and Underlayment	<ol> <li>Use proper and sharp tools.</li> <li>Safe work habits.</li> </ol>	
	Chemical Burns from Sealants	1. Use proper PPE as recomme	1. Use proper PPE as recommended by the manufacturer's MSDS.
	Misunderstanding of Personnel	<ol> <li>Pre-work briefing of all pers JHA's.</li> </ol>	Pre-work briefing of all personnel and supervisors using all MSDS, PADS, and IA's.
	Unsafe/unskilled forklift operator	<ol> <li>Designate &amp; authorize trained forklift operators only.</li> <li>Provide forklift operator training with certification.</li> </ol>	ed forklift operators only. ining with certification.
Stock Tools and Materials on Roof	Back Injuries	<ol> <li>Mechanical equipment will be utilized to move tools &amp; mapossible</li> <li>All employees ill be instructed in proper body mechanics</li> </ol>	<ol> <li>Mechanical equipment will be utilized to move tools &amp; materials whenever possible</li> <li>All employees ill be instructed in proper body mechanics</li> </ol>

# Preparatory Phase Checklist

Contract No.:	FY01 Family H	lousing Fort Wainwrig	ht Alaska	Date: 8-2-02			
efinable Feature:	TS 02510 Stor	m Drains					
Sovernment Rep Noti	fied	Not available	Hours in Advance	Yes	No		
Personnel Present:							
<u>Name</u>		Pos	sition	Company/Government			
<ol> <li>Chris Seeley</li> <li>Jeff Crawford</li> </ol>		QC Manager Superintendent		000			
3. Steve	Genoal to	PM		Great	No. Theres		
4. Rick	our yng			DPILL ROADS	46-1000 15		
5. Pat Do	scoll			DPUI	1		
,				<u> </u>			
7							
o							
. Submittals							
Review submittals	and/or submittal lo	g. Have all submittals	been approved? Not Re	equired this TS			
Yes		No					
If not, what item	ns have not been s	ubmitted?					
	÷						
a							
h							
с.							
. Are all materials or		Yes	X	No			
If not, what item	is are missing?	_		/			
$\mathcal{O}_{i}$	hans	x ~ +	GNW S	600			
a. Walv	· boxe	Sac	G1000 5	nop			
b							
С.							
Check approved su	ıbmittals against d	elivered material. (Thi	s should be done as mater	ial arrives.)			
	<b>3.170</b>						
Comments:	N/A						
<u> </u>							
Matarial atorogo							
. Material storage							
Are materials st	arad proparty?	Yes	X	No			
Are materials st	orea property?	res		NO			
If not, what action	on in takon?						
ii not, what actic	m is takem?						
		. /		7 -	,		
Review Plans	teve G	station	re they ma	ay have to eavences fin	move cub		
in let direin	10 Sp.	CITY	1 + 1	Sprance of	9/m		
Comments: H	op side	reel lo-	naintain co	we will a some	~~ (		
03524 ACF	to the	a hall	P. 0/500 0	OC:11. 1.4	ex of no of		

-	W Toaspan to zerou Kel 1900 cument 27-9 Filed Jul 22/2006 Page 150423
Sp	ecifications
るれ!	1. Review each paragraph of specifications.  Lateman to layout - 6/NW to follow 3. 4. and  que culvert inspected after backfill of compaction up to a  culvert, but the fore going any further.
-	2. Discuss procedure for accomplishing the work.  HCCOMPLISHER
-	
-	3. Clarify any differences, Have any supplemental sketches or RFIs been issued that affect this work.
-	
Pr	reliminary Work and Permits Base and Miss Utility contacted, all utilities marked.
	Ensure preliminary work is correct and permits are on file.  Dig Permit on file and approved
	If not, what action is taken?
Te	esting N/A
	1. Identify test to be performed, frequency, and by whom.  Density testing per compaction test plan
	2. When required?
-	3. Where required?
-	4. Review Testing Plan.
-	5. Has test facilities been approved?
s	safety
-	1. Review Hazard Analysis and applicable portion of EM 385-1-1.
-	2. Activity Hazard Analysis approved? GNW to provide prior to stantos
2	2. Activity Hazard Analysis approved?  Work  No  No
CC	DE comments during meeting.


CDED



3230 Palmer / Wasilla Hwy Wasilla, Alaska 99687

PH (907) 376-7690 FAX (907) 376-7691 E-Mail: sphlwas@mtaonline.net

		######################################					
				<b></b>			
To:	Chris Seeley - Osbo	orne Conts.	Fax:	907-356-	2949		
Fron	n: Leanne Hatt		Date:	8/2/2002	<u></u> ,		
Re:	Welding Inspection	Report	Pages	s:6			
cc:							
	☐ Urgent	☐ For Review	□ Ple:	ase Comm	ent	☐ Please Rep	ıly
•	•	9 9		<u> </u>	•	•	•
	Notes:						
	I will be mailing yo	u to the Fairbanks PC	) box the	originals.			
	Thank you,						
	Leanne						
				,			
						*-	
			.   .				
	ape (1	2002					•
	CONTROL OF THE PROPERTY OF THE						



PH (907)376-7690 FAX (907)375-7891 E-Mail: sphiwas@mtaonline.net

August 2, 2002

Osborne Construction PO Box 73370 Fairbanks, AK 99707

Wasilla, Alaska 99687

Attention: Chris Seeley Re: Fy-01 Ulitidor

Please see attached Welding Inspection report. I have made (8) copies for your distribution. If you have any questions, call us at 907-376-7690, or our North Pole number 488-3359.

Thank you,

Leanne Hatt

Leanne Hatt Project Assistant

# CERTIFIED REPORT OF NONDESTRUCTIVE TESTING VISUAL EXAMINATION

		·····				
	CURTUMPX Slays	den Plumbing & Heating	}	1	DATE	27-Jul-02
KTAN	ADDETES.	1999 Richardson H	ighway, North	Pole AK 997		072702-01
	ght Housing Projec	<u>1999 Richardson H</u> t	THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN	V.a.NO		OR DWG NO.
ARRACK COMPATION As Welde	xt	PEAT NO.	N/A	MUAT TREAT	APTUR.	NA CS
EXAMENATION STANDARD:	ME Section V	ACCEPTANCE STANDA	ANSI			NDE-VT-001
TUTAL AMOUNT EXAMINED 100%	VT	TYTE OF WORK	NO. ACCS	710D:	NO. KILLICAIU	
Visual inspection is being	nerformed on 100%			***	the steam and co	ndensate
piping in accordance with a				,		
B31.1 are being marked an			_			
Scott McCumby and Earl I	lutchinson of which	h, two were rejected, on	for porosity a	nd one for his	omplete penetrat	lon.
Both welds were made by I	Earl Hutchison, the	se welds were repaired a	md radiograph	y was perform	ed on them plus	an additional
four welds as required by A	NST / ASME BEL	i. all wolds were found	accentable.			
Visual inspection has not fi				ls were inspec	ted after the well	is were
complete but random inage						47444 A
followed.				.		
Daily notes are being kept a	and will be convert	ed to a final inspection t	court when all	wolding is co	molete. Radioen	phy
requirements will tracked a						
wolds are now being used o		<del></del>		<del></del>		
penetration Welds vs. socke		term hills torte ma testa se				
pendunikan weng va. socaç	L WEILLS.		<del></del>	1		
			<del></del>	1.		
		······································	····	1		
	<del></del>	<del></del>	·	<u> </u>		
•					·	
		,,,,,				
	<del> </del>	<del></del>	**************************************			
- /	7	· • · · · · · · · · · · · · · · · · · ·	<del></del>		,	
TECTROCIAN (		S a Will	AMERIAN	N/A 1		
TRICTINETAN: RIA	1000	BDD MG	AMERIANI			
		,,	A STATE OF			<del></del>
START TIME	TOTAL MILEAGE:				, m:	: DF 1
FINISH TIME:	444 (11944) 4 4 4 4				PACE	
STANDBY: Hrs. TRAVEL: Hrs.	CUSTOMER:	CIGINTU	<u> </u>			
LUNCH HIS		interfall As				
TOTAL TIME: Hrs						
Belleving and Haliff dalaties				•		

IERY AVE YUE I(XA9)

į

P.275

Quality through integrity

F.O. Box 221051 Ancionago, Alasina 99522-1051 Office: (907) 345-5567 = Fax (967) 346-7353

1218 Gilmora Trail Fairbanks, Alaska 99712 Odlice: (997) 474-2018 • Fast (907) 474-2018

ACC	V	Par	Comments Por D N >.650"	Date 1/20 OZ Report No. 1 Page 1 of 2 Customer 1/26 Character 1/25 Job Number 1/26 Job N
\ \ \ \		Par	7.000	Job Number  Job Name DACA RE-ON-E-DARLE  Time at Job Ster Lifes Driving Time wide
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				Time at Job siteOriving TimeOriving Time
~				Time at 100 pits
~				
		ļ <u>-</u>		TECHNIQUE INFORMATION
	سند	1	1	I am a demonstration of the body
		<b>∓P</b>		Pipe Diameter 2. Material Unicaries - 12. Inches 16192 Curies 56. Exp. Time 4. Source to Film Distance 22.
<u> </u>	+-			Source to Object Distance 19.655
	+	<del> </del> -	<u> </u>	Physical Source Size -   12.4 × 11.6 Effective Pocal Spot _ 152
<del>\</del>	<del> </del>	1	<del>                                     </del>	Geometric Linchestress Factor (UG) - 218
3 1	+	-	Por YET	No. of Beposures/weld_3_
				Peneramenter 12 Shim 540 Exposure Technique P42 6 D42V
V				Ph Screen Front - DIO Bank - DIO
5 1	<u> </u>	<u> </u>		Dev. Time 4 10 Dev Temp. 6 8
			<del> </del>	
<del></del>		<del> </del>		DEFECT ASBREVIATIONS
<del></del>	<del></del>	+	<del> </del>	P. Porosity St. Stag Line TI- Tung. Incl. C. Crack CC Crace Crack SI- 51ag Inclusion
	+	-	<del>-</del>	CV- Conceptity CX- Conventty
	<del> </del> -	+	<del>                                     </del>	IF- Incomplete Fusion IF- Incomplete Penetratio
	_	1	1	ET- Sura Through ILI- Internal Usder cut EU- Emercal Undercut
				190- Incomplete penetration due to High Low
				GP- Cas pocket SP- Spherical Porcetty CP-Cluster Porosity WP Wernshole Porosity
				HB- Hollow Bead
ころ	J	<b>56</b> 25		LEVEL II
TECH	NICIA	N ALL D	4.1	LEVEL ASST
	TECH	TECHNICIA	TECHNICIAN	TECHNICIAN

Rx Date/Time

JUL-30-2002(TUE) 15:00

9074882711

.P. 004

07/30/2002 15:26 9074882711 JUL-31-2002 01:14 FROM:

SLAYDEN

TO:4862711

PAGE 04 P.3/5



Quality through Integrity

P.O. Bozz 22 105 i Appliotrago, Alanka 99922-105 i Odfor: (907) 345-3967 o Fax (907) 346-7333

7212 Gibrare Yesil Fairburks, Alleka 99712 Office: (907) 474-2088 = Fax (907) 474-2088

Weld LD, No. Piece or Line No.	Films Ci 1	ACC	REJ	Mofaet	Comments	Dato is 129 202 Report No. 1
ش - آع	A	مسن	·			Customer NFOG Constitute The 15%
3	8	1				Job Location   Fig. 11 August 1997   A.S.: Job Name   DACA 52.5
	4	-				Time at Job site 4/a Driving Time AVA
······································	1					
دس - ۱۹	4	1	<u> </u>			TECHNIQUE INPORMATION
-7	8	V				Pipe Diameter (5" Material Thickness ZAD Isotope (R + 192 Curies 58 Exp. Time 4")
·····	<u></u>	-				Source to Frim Distance 22
· · · · · · · · · · · · · · · · · · ·						Source to Object Distance 20.1
CW - 19	A	-	-			Physical Source Size T16-2 .126 x .110
	G	-			-	Geometric Uncharpment Factor (UG) . 614
	٥	1				No. Film per essectio No. of Exposures/weld 1
	<b></b>	1				Penetrameko 16 Shim 1500 Esperara Technique OSE ONU
6 <del>44 - 25</del>	A	-			,	STAND OFF SUPER IMPASE
	8	-				Ph Screens Front 'DIO Back OFD  Dev. Time ( SP Dev Temp. 49'
	2	-				Dev. Time 1 Sp 4 Dev Yemp. 48'
			1		•	DEFECT ABBREVIATIONS  P. Pomeiro SL. Size Line Ti-Tung, Incl.
		1	<u> </u>			P. Porceity SL. Slag Line TI-Tung, Insl. CCrack CC-Crater Crack SI- Slag Inclusion
						CV-Concevity CX-Convexity
<del></del>	-		<del>                                     </del>	1		IF- Incomplete Fusion IP- Incomplete Posetration BT- Bran Through IU- Internal Under out
						BT-Burn Through IU-Internal Under out EU-Ememal Undertun
		1	<u> </u>			IPD- Incomplete percention due to High Low
	-		<b> </b>	1		CP- Gas pocket SP- Spherical Porosity CP-Charges Foresity WP Wormhole Perosity
	<del> </del>		-	<del> </del>		CP-Cluster Peresity WP Wormhole Peresity HB- Hollow Bend
	<u></u>	1	<u> </u>	J.q.	<del></del>	LEVEL II
1		1ECHν γομ			<u> </u>	
-	L	HYN	Z.	140	64 <u>4</u> 2172	LEVEL ASST

PAGE 05



# QUALITY INSPECTION & TESTING INC.

3001 International Street • Foirbanks, Alarka 99701 Phone: (907) 479-4273 • Fax: (907) 479-8072

PERILING. WHO PERING. NO. NO.	ijira Ne.	ACE			<b>,</b>	7.9.0.2
		1 40-32 1	120	Code	metalan XS	00/
"CMC 5W-194						MADIOOPSIPHT BEPORT NO
	<b>X</b>			7	-045" -A	MGI
	<u></u>					CURRENT AL DEL CARRELE THE TO
		ļ	<del> </del>	<b>-</b>		Address
SW-3081	<u></u>	1	<u> </u>	<del> </del>		Jois Localiba
	<u> </u>		-			Job Localize  Curdicings P.O. No.
			<u> </u>	-		Transport Committee Commit
\		\	<u> </u>			Description Certain Propriet University No.
						MONK CININGS
						tyliga Use
		-	<del>-</del>	$\top$		
				-	<del></del>	
			<del></del>		<del> </del>	n annual in the
		1			<u> </u>	2.32£ 2
			1	<u> </u>		MI
				7		- 1ypa 0
	->~			<del> </del>	_	TECHNOLIS DATA
		<u>_</u>				Imposite Special ASME
						A CONTRACTOR OF THE PARTY OF TH
	1					AT PRODUCTION,
	1		X	1		Single Marie (Carry)
	<del>                                     </del>	_	_			Single West Expension (SPE) Decision Management (SPE) Decision Managem
	<u> </u>			-}-		Project States State and Control States to Contr
		<u> </u>			<b>\</b>	Haland Tolchipa 2.56 Type learned _C/S
	1			_		A17
	+		7	7		1 Properties The contract
	<u> </u>	<del>-                                    </del>				The state of the s
			-		<del></del>	Po Scores From D / D Corps
	1.					13/20/24   NW /12/4 / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24   / 11/20/24
					[	AMERICALISM OF MASTERING DESCRIPTS
1. TCGGGS	SIAN CIAN		d-	U	VEL	P - Porestly St Size Librar  O - Ceacle F - Incomplate Fysion BY - Incomplate Personnian UC - Lockeruit  ON - Celulation ON - Celulation
1 Maria	-/			LE	VEL	ABBREVATION OF WELDERS DEPARTS.
2	<b>EM</b> /7	,			-	API STANDARD
3. TECHNICIANS	C SAPARE	SR.		u	EVEL	(F - jesziegusty Persymbol)
TECHNICIAN	e Chianny			1	EVEL	TC - PERSONAL CONTRACTOR OF THE SECOND CONTRAC
4. CUSTOMERE	RIGNATUR	Ē				in - Jugaraphete Pusión  IFO - incomplete Fusión due la Cold Lap  Co-Crecia  Co-Crecia  Co-Crecia
					المعالمات المستنا	AT - Team Throught 10 min
Approximates Frince	un iestopus	billy lo	10220	s of arry	ring waich Watation	CO2 - Executation Storp involved EU - Executat Uniterest

F.5/5



# QUALITY INSPECTION & TESTING INC.

3001 Internotional Street - Fortunks, Aleska 99701 Photos: (907) 479-4273 - Fast (907) 479-8072

				7		Arabira				
BERIAL HO.	-	Film		ST'A	Defeat Carin	- SHARKS	DATE	7.12.03		
OA PACE SO.	No.	No.	ACC	HET.			AND CONFINED	GET 160.		
			[	1			MGH	1		
WEKNATE	Car B.Z.							DE CONSULT	ANTE TOP	
l			<b>/</b>	╁─╌	╁		Customer	CD E COLONIE		
		_	1_	<u> </u>			- Address			
	<del> </del>				1	ļ	<u> </u>			
	C41.28	<del></del>	1	<del> </del>	<del> </del>		Job Location	T CARLO SECTION NO.		
				<del> </del>	<del> </del>					
		٠.	1	1 _	<u> </u>		nem Description			
		· · · · · · · · · · · · · · · · · · ·			1		Employee: Parts	i		
	Jeu-29		+-	<del> </del>	╅┈		Politi de Cranifis, Na			
	7	12	1/		<b>↓</b>			ALONE SCHOOL THA		
				1	1		- Km4	(am Descriptor)	Offering	
		}_E	+-	1	1		φî			
_	<u> </u>	_A_	<del>\</del>	+-		- <del> </del>		ina, !	Spirithy	
		P		_1_	<u> </u>				9	
	- <del> </del>	-			T.			Figure Water 1 2 person les con	<u> </u>	
<u> </u>		<del></del>		-	<del>-  </del> -	1		T. T. C. T. P. T.	_ 9	
<u> </u>	] _		__			<del></del>	<b>-1</b> -12-5	7,70		
	_	7	- (	- 1						
			$\neg$	$\neg \vdash$		`		TRESPRESANT CATA		
		_\	+		_		Investiga State	ACME T	NES	
		<u> </u>								
				_l			HT Precedure 7th	: Sales o 🖈 د سند. ا	PSSAI	
			∤	-+-			Single With 1780		Double Was Frankly (DWA)	
							<del></del>	l 👝	PART NO. CALLED TO THE PART OF	
		7	V				Physical Source	Time Last 2110 Claring Tax	21.91	
		_	_					2 4 DM to produce		
			╼┷┼╌	-	<		Newson junction	2 ARC Type Marenial		
		1			}-			Approximate (A)	Tro _073	
				- 1	-	1				
							Name(# Single		Back	
					╌╋	_		The state of the s	1- Same 62 6	
						_	Second Tife	12.50 to 11 A		
		_			_ ` <b>\</b>	<b>\</b>		ABBRONUNDON OF WELDING DE	14012	
								ASME CODE	Detailers indepent . IT	
						-0.000		81 - Stag Inchesions	CY - Hotel Concavily Cit - Real Convenity	
1	COLLEGE				Ь	EVEL	III., Incorrig	AND FUNCES BY A SUMMER OF THE SUMMER OF THE SUMMER OF THE SUMER OF THE SUMMER OF THE SUMER OF THE SUMMER OF THE SU	CIX - Candralyou	
1	TECH	MCIAN	•			GUET	er-Incluit	AND REVERTISM OF SET CAND D	EFECTS	
, , ,	MASSE	·			' _t	EVEL		API STANDARD		
	TEC	MICIAN	2			13.75i	amban	Andrea of Circumstitishing	Sp Edward Barrel Ca Edward Barrel	
9 54	C.Can	مركوس		<del></del>	¹	EVEL		AND PROCESSION OF IN HIGH-TIME.	ann Chualan Child IV	
	THCHOCKS	PATER PAT	ψ.			Lavel	\$ IC. Iniden	al Concert?	WP - Wanting Perceity	
А			-74			FB A CT		Planto Fundon Implifish Fundon cour Lo Cotal Liab	CC - Citola Cuech C - Cuech	
4. <del> </del>		A'S SIGNATU							IT I I THE THE LIGHT	
	Q.I.T. assums	ය එය අත්සියක්	albinty (	or l <b>oos</b>	na <b>of</b> an	y kind which	PORT Class	red god luc _{ing} ane Pered and lucymous	EU - External Underqui	
	CT.1.1. SESTIMA	nodeoi on g Dialoeb to to	ne at w	igans	ni ar inl	Sibiologica.	EM - 194/	1		